

February 7, 2018

Donald V. Stanley Trust  
7100 S. Lincoln St.  
Centennial, CO 80122

Re: Well Re-Entry and Mitigation  
Colorado Oil and Gas Conservation Commission ("COGCC") - DJ Basin Horizontal Offset  
Policy

**TOWNSHIP 8 NORTH, RANGE 60 WEST, of the 6th P.M.**

SECTION 22: SE/4  
Weld County, Colorado  
(the "Lands")

Per the COGCC DJ Basin Horizontal Offset Policy, any existing oil and gas wells within 1500' of a proposed horizontal wellbore that does not have adequate protection and isolation over the treated formations must be re-entered and mitigated prior to hydraulic stimulation of the proposed horizontal wellbore. The following well(s) on your Lands do not meet the COGCC standards and must be mitigated prior to Mallard's hydraulic fracturing operations:

- STANLEY #0 (API: 05-123-1459) a/k/a Stanley-68N60W #22SWSE

Mallard is required to enter your Lands in order to locate, unearth, re-enter, and mitigate these existing plugged and abandoned wells prior to hydraulic fracturing operations. This process will take approximately ten days from commencement to completion.

Please sign below consenting to Mallard Exploration, LLC and/or its contractors or agents entering your Lands located in Weld County, Colorado in order to perform the above-described work.

If you have any questions or concerns, please do not hesitate to contact me at the following:

E-mail: [jlinton@wildcatresourcesinc.com](mailto:jlinton@wildcatresourcesinc.com)  
Cell: 303.882.8472  
Office: 720.543.7951

Respectfully,

John Linton  
Wildcat Resources: Surface Landman

As owner of the Lands, I/We hereby consent to Mallard Exploration, LLC and/or its contractors or agents to enter the Lands in Weld County, Colorado in order to mitigate the STANLEY #0 (API: 05-123-1459) a/k/a Stanley-68N60W #22SWSE well in accordance with the Colorado Oil and Gas Conservation Commission's- DJ Basin Horizontal Offset Policy.

Surface Owners:

**The Donald V. Stanley Trust**

Ruth Stanley, Trustee  
Ruth Stanley, Trustee