

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/08/2019

Submitted Date:

02/08/2019

Document Number:

695100146**FIELD INSPECTION FORM**

Loc ID 307498 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217743	WELL	PR	02/12/2003	GW	071-06522	MOLTRER 31-7	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN NOT POSTED/ NO EMERGENCY CONTACT NUMBER POSTED.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	07/30/2018

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Compressor	# 0		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 217743	Type: WELL	API Number: 071-06522	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Storm water washed blown down below location see attached photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 07/30/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Followup inspection to inspection doc 688400211. Not all corrective actions have been completed.	beardslt	02/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401934297	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729713
695100151	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729703