

GOLDEN EAGLE 28-16 API # 05-071-07989 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401103



PHOTO 1: REPLACED PACKING TO ELIMINATE THE WATER LEAK

GOLDEN EAGLE 28-16 API # 05-071-07989 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401103



PHOTO 1: REPLACED PACKING TO ELIMINATE THE WATER LEAK

PHOTO 2: THE STAINED SOIL AROUND THE ENGINE SKID WAS CLEANED UP.

GOLDEN EAGLE 28-16 API # 05-071-07989 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401103



PHOTO 3: THE STAINED SOIL AROUND THE ENGINE SKID WAS CLEANED UP.

GOLDEN EAGLE 28-16 API # 05-071-07989 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401103



PHOTO 4: THE STAINED SOIL BELOW THE 1 INCH DRAIN LINE WAS CLEANED UP.