

APACHE CANYON 03-05 API # 05-071-06268 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100050



PHOTO 1: REPLACED PACKING TO ELIMINATE THE WATER LEAK.

APACHE CANYON 03-05 API # 05-071-06268 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100050



PHOTO 2: THE STAINED SOIL ON THE GROUND WAS CLEANED UP.

APACHE CANYON 03-05 API # 05-071-06268 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100050



PHOTO 2: THE STAINED SOIL ON THE GROUND WAS CLEANED UP.

APACHE CANYON 03-05 API # 05-071-06268 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100050



PHOTO 4: THE DIRT BERM WAS REPAIRED.

APACHE CANYON 03-05 API # 05-071-06268 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100050



PHOTO 5: THE DIRT BERM WAS REPAIRED.