

APACHE CANYON 31-12 API # 05-071-09120 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401128



PHOTO 1: THE STAINS ON THE GROUND HAVE BEEN CLEANED UP.

APACHE CANYON 31-12 API # 05-071-09120 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401128



PHOTO 2: THE LIQUID RING SKID HAS BEEN CLEANED AND THE ACCUMULATED FLUID WAS REMOVED FROM THE RESERVOIR. THE STAINS ON THE GROUND HAVE BEEN CLEANED UP AS WELL.

APACHE CANYON 31-12 API # 05-071-09120 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401128



PHOTO 3: THE LIQUID RING SKID HAS BEEN CLEANED AND THE ACCUMULATED FLUID WAS REMOVED FROM THE RESERVOIR. THE STAINS ON THE GROUND HAVE BEEN CLEANED UP AS WELL.

APACHE CANYON 31-12 API # 05-071-09120 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401128



PHOTO 4: THE LIQUID RING SKID HAS BEEN CLEANED AND THE ACCUMULATED FLUID WAS REMOVED FROM THE RESERVOIR. THE STAINS ON THE GROUND HAVE BEEN CLEANED UP AS WELL.

APACHE CANYON 31-12 API # 05-071-09120 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401128



PHOTO 5: THE ABSORBENT PADS WERE REMOVED FROM THE LIQUID RING SKID AND THE SKID WAS CLEANED. THE ACCUMULATED FLUID WAS REMOVED FROM THE RESERVOIR. THE STAINS ON THE GROUND HAVE BEEN CLEANED UP.

APACHE CANYON 31-12 API # 05-071-09120 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 15, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401128



PHOTO 6: ALL THE STAINS ON THE GROUND HAVE BEEN CLEANED UP.