

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2019

Submitted Date:

02/11/2019

Document Number:

679400287

**FIELD INSPECTION FORM**

Loc ID 319937 Inspector Name: CHESSON, BOB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 12400  
Name of Operator: BYRON OIL INDUSTRIES INC  
Address: 154 CLARKSON EXECUTIVE PARK  
City: BALLWIN State: MO Zip: 63011

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
BYRON, RICHARD	636-391-8770	byronoil@aol.com	<a href="#">ALL INSPECTIONS</a>
Gomez, Jason		jason.gomez@state.co.us	

**General Comment:**

Inspection for production pit closure (remediation #12152). Pit unclaimed. Stockpiled soils material on lease. Stockpiled soils must be removed to appropriate disposal by 3/8/19.

Stormwater erosion on southern edge of PW pit. Stormwater erosion controls must be repaired and/or enhanced by 3/8/19.

Production pit will remain as "active" status until reclaimed. Operator will file sundry notice to EPS when pit has been reclaimed.

See photos.

**Location Construction**

Location ID: 319937 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** Stormwater erosion on southern end of PW pit.

**Corrective Action:** Beef-up stormwater controls on southern end of PW pit.

Date: 03/08/2019

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_



**Environmental**

**Spill/Remediation:**

Comment: 
  
 Corrective Action:  Date:

Emission Control Burner (ECB): 
  
 Comment: 
  
 Pilot:  Wildlife Protection Devices (fired vessels):

**COGCC Comments**

Comment	User	Date
<p>Inspection for production pit closure (remediation #12152). Pit unclaimed. Stockpiled soils material on lease. Stockpiled soils must be removed to appropriate disposal by 3/8/19.</p> <p>Stormwater erosion on southern edge of PW pit. Stormwater erosion controls must be repaired and/or enhanced by 3/8/19.</p> <p>Production pit will remain as "active" status until reclaimed. Operator will file sundry notice to EPS when pit has been reclaimed.</p> <p>See photos.</p>	chessonr	02/06/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401935210	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4730592">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4730592</a>
679400288	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4730586">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4730586</a>