

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401943756
Date Received:
02/19/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rowley, Darren

drowley@logosresourcesllc.com

Sessions, Tamra

tsessions@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603428

Inspection Date: 12/18/2018

FIR Submit Date: 12/26/2018

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325196

Location Name: BONDAD 33-10-N33N10W Number: 13NWNW County: LA PLATA

Qtrqr: NWN Sec: 13 Twp: 33N Range: 10W Meridian: N

Latitude: 37.108690 Longitude: -107.891660

FACILITY - API Number: 05-067- -00 Facility ID: 214257

Facility Name: BONDAD 33-10 Number: 7

Qtrqr: NWN Sec: 13 Twp: 33N Range: 10W Meridian: N

Latitude: 37.108690 Longitude: -107.891660

CORRECTIVE ACTIONS:

1 CA# 121326

Corrective Action: Remove waste and debris.

Date: 01/18/2019

Response: CA COMPLETED

Date of Completion: 01/18/2019

Operator
Comment:

Debris within the rig anchor pattern has been removed. We do not have a surface use agreement with the surface owner and do not have the authority to remove the land owners personal property. The personal property of the land owner that is located outside of our rig anchor pattern does not affect the public's health and safety or our ability to operate the well in a personal or environmental safe manner. However, we have contacted the land

owner and they are willing to relocate their equipment.

COGCC Decision: **Not Approved**

COGCC Representative: Logos Resources is responsible for the entire project area, not just the area within the rig anchor pattern. Location will remain out of compliance until corrective actions are addressed and if not addressed, may be subject to enforcement.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed:

Title: Environmental Technician

Date: 2/19/2019 10:20:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401943756	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files