

GOLDEN EAGLE 30-14 API # 05-071-08650 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 19, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401124



PHOTO 1: THE STAINS ON THE GROUND AROUND THE LIQUID RING HAVE BEEN REMOVED.

GOLDEN EAGLE 30-14 API # 05-071-08650 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 19, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401124



PHOTO 2: THE MATERIAL FROM THE PORTION OF THE CUT SLOPE THAT SLOUGHED OFF WAS REGRADED BACK TO THE ORIGINAL GRADE. GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR FOR TEMPORARY SOIL STABILIZATION. THE DISTURBED SOIL ON THE CUT SLOPE WILL BE HYDRO-SEEDED USING THE APPROVED COLORADO PARKS AND WILDLIFE SEED/SCRUB MIX, ALONG WITH FERTILIZER, SOIL ENHANCER & FLEXTERRA FLEXIBLE GROWTH MEDIUM DURING THE NEXT FAVORABLE GROWING SEASON.

GOLDEN EAGLE 30-14 API # 05-071-08650 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 19, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401124



PHOTO 3: THE DIRT BERM SURROUNDING THE PRODUCTION PIT WAS DOMINATED.

GOLDEN EAGLE 30-14 API # 05-071-08650 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 19, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401124



PHOTO 4: THE SOIL THAT SLOUGHED OFF INTO THE PIT WAS REMOVED.