

GOLDEN EAGLE 33-04 API # 05-071-09507 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401109



PHOTO 1: THE ACCUMULATED FLUID WAS REMOVED FROM THE LIQUID RING SKID.

GOLDEN EAGLE 33-04 API # 05-071-09507 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401109



PHOTO 2: THE LIQUID RING SKID AND STAINS ON THE GROUND WERE CLEANED UP.

GOLDEN EAGLE 33-04 API # 05-071-09507 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401109



PHOTO 3: THE SOUND WALL PANEL WAS REMOVED FROM LOCATION.

GOLDEN EAGLE 33-04 API # 05-071-09507 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401109



PHOTO 4: THE ELECTRIC FENCE WAS REPAIRED.

GOLDEN EAGLE 33-04 API # 05-071-09507 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 21, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401109



PHOTO 5: THE NEW LOCATION SIGN WAS INSTALLED ON THE SEPARATOR HOUSE.