

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401950459  
Date Received:  
02/25/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10177  
Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION  
Address: 950 17TH STREET #2200  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Scott Mason</u>	<u>720-279-5581</u>	<u>scottmason@enerplus.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404260  
Inspection Date: 12/14/2018 FIR Submit Date: 12/17/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ENERPLUS RESOURCES (USA) CORPORATION Company Number: 10177  
Address: 950 17TH STREET #2200  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449968

Location Name: Colorado Lakes Number: Pad County: \_\_\_\_\_  
Qtrqr: SWS Sec: 28 Twp: 8N Range: 67W Meridian: 6  
W  
Latitude: 40.628235 Longitude: -104.904830

FACILITY - API Number: 05-123-00 Facility ID: 449968

Facility Name: Colorado Lakes Number: Pad  
Qtrqr: SWS Sec: 28 Twp: 8N Range: 67W Meridian: 6  
W  
Latitude: 40.628235 Longitude: -104.904830

CORRECTIVE ACTIIONS:

1 CA# 121110

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control and manage weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 01/14/2019

Response: CA COMPLETED Date of Completion: 01/17/2019

Weeds were mowed. Spraying for weeds and re-seeding will occur in early spring.

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

**3** CA# 121112

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/14/2019

Response: CA COMPLETED

Date of Completion: 02/25/2019

Operator  
Comment:

Section of the lease road ditch where erosion was observed will be entirely reclaimed. During negotiations with the surface owner to allow construction of our Colorado Rivers Pad south of Colorado Lakes, it was agreed that portions of this road would be re-located to the south. As such, this portion of the lease road will be entirely reclaimed and re-seeded. Construction of the new lease road is anticipated to begin the week of March 3rd.

Enerplus will complete an engineering road design of the new road to determine if check dams along the new lease road will be necessary.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: We are still working with the landowner to get a signed delay of interim reclamation letter for this pad. We should have this and file the request for delayed interim reclamation within the next week.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Mason

Signed: \_\_\_\_\_

Title: Team Lead - Environmental

Date: 2/25/2019 2:23:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files