

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401950459

Date Received:

02/25/2019

FIR RESOLUTION FORM

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Scott Mason

720-279-5581

scottmason@enerplus.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404260

Inspection Date: 12/14/2018

FIR Submit Date: 12/17/2018

FIR Status: _____

Inspected Operator Information:

Company Name: ENERPLUS RESOURCES (USA) CORPORATION

Company Number: 10177

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449968

Location Name: Colorado Lakes Number: Pad County: _____

Qtrqr: SWS Sec: 28 Twp: 8N Range: 67W Meridian: 6
W

Latitude: 40.628235 Longitude: -104.904830

FACILITY - API Number: 05-123- -00 Facility ID: 449968

Facility Name: Colorado Lakes Number: Pad

Qtrqr: SWS Sec: 28 Twp: 8N Range: 67W Meridian: 6
W

Latitude: 40.628235 Longitude: -104.904830

CORRECTIVE ACTIONS:

1 ☒ CA# 121110

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control and manage weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 01/14/2019

Response: CA COMPLETED

Date of Completion: 01/17/2019

Weeds were mowed. Spraying for weeds and re-seeding will occur in early spring.

Operator
Comment:

COGCC Decision: Approved

COGCC Representative: Field Inspection Report Doc.# 682404503 conducted on 2/11/2019 confirmed the Operator performed the corrective action.

3 ☒ CA# 121112

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/14/2019

Response: CA COMPLETED

Date of Completion: 02/25/2019

Operator Comment: Section of the lease road ditch where erosion was observed will be entirely reclaimed. During negotiations with the surface owner to allow construction of our Colorado Rivers Pad south of Colorado Lakes, it was agreed that portions of this road would be re-located to the south. As such, this portion of the lease road will be entirely reclaimed and re-seeded. Construction of the new lease road is anticipated to begin the week of March 3rd.
Enerplus will complete an engineering road design of the new road to determine if check dams along the new lease road will be necessary.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

Field Inspection Report Doc.# 682404503 conducted on 2/11/2019 confirmed the Operator made repairs but failed to install additional BMPs. It appears the repairs have temporarily stabilized the access road until the planned Final Reclamation of the access road. Note: Appears the Operator has made repairs to the silt fence that were previously observed; however, BMP is in need of maintenance.

OPERATOR COMMENT AND SUBMITTAL

Comment: We are still working with the landowner to get a signed delay of interim reclamation letter for this pad. We should have this and file the request for delayed interim reclamation within the next week.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Mason

Signed: _____

Title: Team Lead - Environmental

Date: 2/25/2019 2:23:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401950459	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files