

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401951108

Date Received:

02/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26580

Name of Operator: BURLINGTON RESOURCES OIL & GAS LP

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Liang Yu

Phone

8324866014

Email

liang.yu@cop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902469

Inspection Date: 02/01/2019

FIR Submit Date: 02/14/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BURLINGTON RESOURCES OIL & GAS LP

Company Number: 26580

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 453244

Location Name: Cottonwood Creek Number: 4-65 27-28 County: \_\_\_\_\_

Qtrqr: SWSE Sec: 27 Twp: 4S Range: 65W Meridian: 6

Latitude: 39.668572 Longitude: -104.645950

FACILITY - API Number: 05-005- -00 Facility ID: 453244

Facility Name: Cottonwood Creek Number: 4-65 27-28

Qtrqr: SWSE Sec: 27 Twp: 4S Range: 65W Meridian: 6

Latitude: 39.668572 Longitude: -104.645950

CORRECTIVE ACTIONS:

1 CA# 122514

Corrective Action: Reclaim all areas not needed for production. There may be room at the center of the location and the northwest of the location. Interim reclamation should have been completed by 2/1/2018.

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator Comment: The room at the center of the location and the northwest of the location is reserved as the reasons below:  
1) Space for truck routing  
2) Space for workover rig  
3) Space for future artificial lift equipment  
4) To reclaim these areas it would unearth the flowlines.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 122515

Corrective Action: Perform erosion repairs. Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Install or repair required BMPs per Rule 1002.f.

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator  
Comment: Repaired BMPs per Rule 1002.f. Please see attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liang Yu

Signed: \_\_\_\_\_

Title: Sr Regulatory Coordinator

Date: 2/26/2019 1:03:14 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401951109	Post BMP Repair Photo
-----------	-----------------------

Total Attach: 1 Files