

FORM
6Rev
05/18State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Replug By Other Operator

Document Number:

401954923

Date Received:

02/28/2019

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:	5	Contact Name:	Dave Andrews
Name of Operator:	COLORADO OIL & GAS CONSERVATION	Phone:	(303) 894-2100x5686
Address:	1120 LINCOLN ST SUITE 801	Fax:	
City:	DENVER	State:	CO
Zip:	80203	Email:	david.andrews@state.co.us
For "Intent" 24 hour notice required,		Name:	Wentzel, Dougo
		Tel:	(970) 986-7314
COGCC contact:		Email:	dougo.wentzel@state.co.us

API Number	05-077-10326-00	Well Number:	1
Well Name:	GEOWELL	Location:	QtrQtr: SESW Section: 21 Township: 8S Range: 97W Meridian: 6
County:	MESA	Federal, Indian or State Lease Number:	
Field Name:	DE BEQUE	Field Number:	16150

☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude:	39.340528	Longitude:	-108.225667
GPS Data:			
Date of Measurement:		PDOP Reading:	
Reason for Abandonment:	<input type="checkbox"/> Dry	<input type="checkbox"/> Production Sub-economic	<input type="checkbox"/> Mechanical Problems
<input checked="" type="checkbox"/> Other	Orphan Well Program Plugging		
Casing to be pulled:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Estimated Depth:
Fish in Hole:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	If yes, explain details below
Wellbore has Uncemented Casing leaks:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	If yes, explain details below
Details:	Fish in hole consisting of wood and rock debris at approximatley 8' deep. Small pond at surface.		

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
MESAVERDE	270				

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	13	6	0	30	0	0	0	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ 270 ft. with _____ 220 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ 100 ft. with _____ 220 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ 50 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: _____
of _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

This well to be plugged by COGCC as part of the Orphan Well Program.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Dave Andrews

Title: OWP Manager Date: 2/28/2019 Email: david.andrews@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Chollett, Shannon Date: 2/28/2019

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 8/27/2019

COA Type Description

COA Type	Description
	1)Provide 48 hour notice of plugging MIRU via electronic Form 42.

Attachment Check List

Att Doc Num	Name
401954923	FORM 6 INTENT SUBMITTED
401954942	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Well File Verification	Well file not found for verification - passed task	02/28/2019
Agency	No information for me to review, all decisions are from engineer	02/28/2019

Total: 2 comment(s)