

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2019

Submitted Date:

03/07/2019

Document Number:

693900033**FIELD INSPECTION FORM**Loc ID 436788 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections
Kosola, Jason		jason.kosola@state.co.us	
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	All Inspections
Hart, Tim		thart@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437153	WELL	TA	03/31/2016	LO	043-06226	Hudson 1	RI

General Comment:This is an interim reclamation and stormwater inspection.

Location Construction

Location ID: 437153 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: Well cellar is largely open (with exception of gate and tire) and could result in wildlife entrapment. Well cellar should be closed to prevent wildlife entrapment. See attached photos.

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: Project area is surrounded by open pinyon juniper woodland, cholla shrub, and grassland. Reclamation activities appear to have been recently conducted. Fencing around project area has fallen apart and is no longer functioning. Livestock/wildlife exclusion may be needed for successful vegetation establishment.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? Fail

Comment: Sign and fencing debris observed around wellhead. Black plastic netting and misplaced wattles are scattered around the perimeter of the project area. Perimeter fence cable is not functioning and is debris.

Corrective Action Remove and properly dispose of debris. Fence should be repaired or removed. Date 04/13/2019Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? In _____ 1003c. Compacted areas have been cross ripped? _____ 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ Cuttings management: _____ 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In _____ Production areas have been stabilized? _____ Segregated soils have been replaced? _____	
--	--

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
-------------------------	-------------------	---------------------------------------

Non-Cropland

Top soil replaced _____	Recontoured _____	80% Revegetation In _____
-------------------------	-------------------	------------------------------

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Due to seasonal conditions, noxious weeds were not assessed during this inspection.

Corrective Action Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____	
Debris removed _____	No disturbance /Location never built _____	
Access Roads Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____		
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	Dust and erosion control _____	
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____	
Weeds present _____	Subsidence _____	

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion appears to be controlled at this time. Erosion should be carefully monitored and managed until vegetation becomes well established and location is stabilized.</p> <p>Corrective Action: <input type="text"/> Date: _____</p> <p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401964841	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755628
693900035	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755626