



<b>Location</b>			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Wellhead Sign is missing Emergency Contact Number		
Corrective Action:	Install sign to comply with Rule 210.b. See Photo 1		Date: 04/19/2019
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 298336 Type: WELL API Number: 123-29036 Status: PR Insp. Status: PR**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_**COGCC Comments**

Comment	User	Date
On 3/18/2019, I Erica Petrie performed an inspection of the Lind 20-53 (Location ID 302377) owned and operated by Great Western Oil & Gas. While on inspection I observed the following issue(s) Wellhead sign missing Emergency Contact Number, see photo 1, Cite 210.b END.	petrie	03/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401976562	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766046">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766046</a>
696300030	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766042">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766042</a>