

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Photo of location at entrance

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Wellhead signs

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Photo of Tank Battery.

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Unused equipment or trash left on location



Trash on location

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Unused and stored equipment on location



Labels missing or faded on white chemical containers

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Stained soil



Stained soil around separators

Caerus Piceance LLC .
Api # 05-045-20521
Inspection # 675002110



Stained soil on location



Stained soil on location