

PA 21-34  
Api. # 05-045-09104  
Inspection # 689702993



PA 21-34  
Api. # 05-045-09104  
Inspection # 689702993



**Dead weed rubbish around wells.**



PA 21-34  
Api. # 05-045-09104  
Inspection # 689702993



**Sediment moving around and into location equipment and tank facility.**

PA 21-34  
Api. # 05-045-09104  
Inspection # 689702993



**Sediment moving around and into location equipment and tank facility.**



**PA 21-34**  
**Api. # 05-045-09104**  
**Inspection # 689702993**



**Sediment moving around and into location equipment and tank facility.**

PA 21-34  
Api. # 05-045-09104  
Inspection # 689702993



**Sediment moving around and into location equipment and tank facility.**