



Sediment trapped cleaned, additional BMPs installed. Standing at the northeast corner of the sediment trap looking south.



Erosion riling corrected and additional BMPs installed to topsoil stockpile.
Looking east at topsoil pile.



East perimeter ditch cleaned and additional BMPs installed. Looking north.



Top of pad cut ditch re-cut. Looking south.