

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

688401807

FIELD INSPECTION FORM

Loc ID 308614 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276542	WELL	PR	06/18/2005	GW	071-08348	APACHE CANYON 14-10	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	stained soil around WH HYD lines		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	05/11/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment; solar panel		
Corrective Action:	Comply with rule 603 f	Date:	05/11/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	Netting on open tanks inadequate. Wildlife protections devices not adequate				
Corrective Action:	Install or repair wildlife protection equipment Per rule 324 A.a				Date: 04/25/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	25bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Silver, Randy

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 276542 Type: WELL API Number: 071-08348 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday April 11, 2019 at approximately 1048 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site AC # 14-10, at API # 05-071-08348 in Las Animas County Colorado.</p> <p>While there, I observed a production well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil; Rule 907 A Corrective action date of 5-11-19 See Photo 5</p> <p>Unused equipment; Rule 603 f Corrective action date of 5-11-19 See photo 2</p> <p>Bird netting; Rule 324 A.a Corrective action date of 4-25-19 See Photo 3</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/11/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401808	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792638