

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402001360
Date Received:
04/15/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Susana Lara-Mesa

303-825-4822

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 678302434

Inspection Date: 04/03/2019

FIR Submit Date: 04/03/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318053

Location Name: GUADAGNOLI-62N67W Number: 30SWSW County: WELD

Qtrqr: SWS Sec: 30 Twp: 2N Range: 67W Meridian: 6
W

Latitude: 40.103640 Longitude: -104.940024

FACILITY - API Number: 05-123- -00 Facility ID: 240510

Facility Name: GUADAGNOLI Number: 1

Qtrqr: SWS Sec: 30 Twp: 2N Range: 67W Meridian: 6
W

Latitude: 40.103640 Longitude: -104.940024

CORRECTIVE ACTIONS:

1 CA# 123817

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Inspect tank to determine if leaking and if leaking cease use and remove product from tank

Date: 04/04/2019

Response: CA COMPLETED

Date of Completion: 04/04/2019

Stained soils within earthen berm next to crude tank and near loadout have been removed. Leaking was fixed. Please see attached pictures.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 123818

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff within 24 hours regarding spill/release volume
clean up stained soils within 30 days if not a reportable spill

Date: 04/04/2019

Response: CA COMPLETED

Date of Completion: 04/04/2019

Operator
Comment:

Stained soils within earthen berm next to crude tank and near loadout have been removed. Leaking was fixed.
Please see attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed:

Title: VP of Engineering

Date: 4/15/2019 10:26:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402008069	Stained soil removed PIC1
402008071	Stained soil removed PIC2

Total Attach: 2 Files