

NEW ELK 24-16 API# 05-071-09473 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401789



PHOTO 1: LOCATION SIGN

NEW ELK 24-16 API# 05-071-09473 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401789



PHOTO 2: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED FROM LOCATION.

NEW ELK 24-16 API# 05-071-09473 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401789



PHOTO 3: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED FROM LOCATION.

NEW ELK 24-16 API# 05-071-09473 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401789



PHOTO 4: THE DEADMAN ANCHORS WERE MARKED WITH RED POSTS.

NEW ELK 24-16 API# 05-071-09473 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401789



PHOTO 4: THE DEADMAN ANCHORS WERE MARKED WITH RED POSTS.