

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402005696

Date Received:

04/12/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Knudson, Dwayne

970-456-3335

dknudson@ursaresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400776

Inspection Date: 03/15/2019

FIR Submit Date: 03/16/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC

Company Number: 10447

Address: 1600 BROADWAY ST STE 2600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 436004

Location Name: Valley Farms Number: O Pad County: \_\_\_\_\_

Qtrqtr: Lot 11 Sec: 10 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.536020 Longitude: -107.657604

FACILITY - API Number: 05-045-00 Facility ID: 436004

Facility Name: Valley Farms Number: O Pad

Qtrqtr: Lot 11 Sec: 10 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.536020 Longitude: -107.657604

CORRECTIVE ACTIONS:

1 ☒ CA# 123272

Corrective Action: Monitor & Control Annual Weeds that become Debris throughout growing season.

Date: 05/15/2018

Response: CA COMPLETED

Date of Completion: 04/11/2019

Operator Comment: Debris has been removed. See photo log

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 123273

Corrective Action: Monitor & Control Noxious Weeds throughout growing season.

Date: 05/15/2019

Response: CA COMPLETED

Date of Completion: 04/11/2019

Operator  
Comment: Debris has been removed. See photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 123274

Corrective Action: There are Four CAs in this Section.

Date: 04/15/2019

1) Stabilize earthen berm. Use long-term methods to stabilize the berms. B Vegetation is preferred long-term stabilization.

2) Install BMP (i.e. Wattle) along inside base of berm to fully segregate and prevent topsoil degradation.

3) Maintain Ditches.

4) Install properly sized and designed sediment trap/s and outlet/s based on the size of location.

Response: CA COMPLETED

Date of Completion: 04/11/2019

Operator  
Comment: Berm has been reseeded and mulched/crimped. Ditches were reworked and outfall was lowered. See photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to Lou Colby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed:

Title: Environmental Manager

Date: 4/12/2019 7:17:35 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

402005696	FIR RESOLUTION SUBMITTED
-----------	--------------------------

402005699	Photo log of repairs
-----------	----------------------

Total Attach: 2 Files