

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PACKING IS STILL LEAKING CAUSING APP. 3' ROUND AREA OF IMPACTED SOIL AROUND WELLHEAD

Corrective Action:

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. 24 HOURS TO REPAIR LEAK. 30 DAYS TO REMOVE IMPACTED SOIL.

Date: 05/15/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217548 Type: WELL API Number: 071-06325 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOWUP TO ISPECTION DOC# 691400642. THE CORRECTIVE ACTION FOR PACKING LEAKING HAS NOT BEEN ADDRESS OR HAS REOCCURRED. THE CORRECTIVE ACTIONS FOR UNUSED EQUIPMENT AND TRASH ON LOCATION HAVE BEEN ADDRESSED.	beardslt	04/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402010230	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4796804
695100511	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4796802