

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402020627

Date Received:

04/24/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Beebe, Sabre</u>	<u>970-779-9398</u>	<u>Sabre.Beebe@bpx.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800485
Inspection Date: 03/26/2019 FIR Submit Date: 04/01/2019 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326167

Location Name: THOMAS JACQUEZ GAS UNIT E-N33N10W Number: 14NESE County: LA PLATA
Qtrqtr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N
Latitude: 37.103177 Longitude: -107.898299

FACILITY - API Number: 05-067-00 Facility ID: 215984

Facility Name: THOMAS JACQUEZ E Number: 1
Qtrqtr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N
Latitude: 37.103177 Longitude: -107.898299

CORRECTIVE ACTIONS:

1 CA# 123735

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Date: 05/01/2019

Response: CA COMPLETED Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk

remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: _____

COGCC
Representative:

2 CA# 123736

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: _____

COGCC
Representative:

3 CA# 123737

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 04/02/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: _____

COGCC
Representative:

4 CA# 123738

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 04/02/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: _____

COGCC
Representative:

5 CA# 123739

Corrective Action: Maintain signs in a legible condition per Rule 210.e.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: sabre.beebe@bpx.com

Signed: _____

Title: Compliance Specialist

Date: 4/24/2019 5:27:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402020628	Photos of work completed on location

Total Attach: 1 Files