

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401978143

Date Received:

04/30/2019

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

463347

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>DCP OPERATING COMPANY LP</u>	Operator No: <u>4680</u>	Phone Numbers
Address: <u>370 17TH STREET - SUITE 2500</u>		Phone: <u>(970) 3786373</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Chandler Cole</u>		Mobile: <u>(970) 9390329</u>
		Email: <u>cecole@dcpmidstream.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401972099

Initial Report Date: 03/14/2019 Date of Discovery: 03/13/2019 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 34 TWP 2N RNG 67W MERIDIAN 6Latitude: 40.087829 Longitude: -104.883628Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: GAS PROCESSING PLANT☒ Facility/Location ID No 412250Spill/Release Point Name: _____ ☐ No Existing Facility or Location ID No.Number: _____ ☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): >=5 and <100Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: OTHEROther(Specify): Gas processing plantWeather Condition: Severe weather conditions, snowingSurface Owner: OTHER (SPECIFY)Other(Specify): DCP Midstream

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On March 13, 2019, a spill occurred from a fire tube leak that was discovered from the heater treater on the stabilized condensate tanks. Operations noticed smoke coming out of the stack that was white. Operations went to investigate and found a steady stream of condensate leaking out of the spark arrestor door which would indict a fire tube leak. Approximately 20 barrels of a mixture of condensate and snow was contained within the secondary containment. Operations shutdown and bypassed the treater and is scoping the repairs. Operations will remove the condensate and snow mixture as soon as possible via hydrovac once the snow has melted and can be recovered. No condensate was released outside of secondary containment.

List Agencies and Other Parties Notified:

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date:	03/19/2019		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown	
OIL	0	0	<input type="checkbox"/>	
CONDENSATE	5	5	<input type="checkbox"/>	
PRODUCED WATER	0	0	<input type="checkbox"/>	
DRILLING FLUID	0	0	<input type="checkbox"/>	
FLOW BACK FLUID	0	0	<input type="checkbox"/>	
OTHER E&P WASTE	15	15	<input type="checkbox"/>	

specify: Snow melt

Was spill/release completely contained within berms or secondary containment? YES Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☐ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 41 Width of Impact (feet): 23

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): _____

How was extent determined?

On March 13, 2019 during the snow cyclone bomb, a leak occuring from a fire tube was discovered leaking from the heater treater on the stabilized condensate tanks. The released condensate mixed with the snow accumaulation within the concrete secondary containment. The concrete secondary containment contained the entire volume of condensate and snow melt mixture.

Soil/Geology Description:

NA

Depth to Groundwater (feet BGS) 8 Number Water Wells within 1/2 mile radius: 62

If less than 1 mile, distance in feet to nearest

Water Well	<u>218</u>	None <input type="checkbox"/>	Surface Water	<u> </u>	None <input checked="" type="checkbox"/>
Wetlands	<u>3473</u>	None <input type="checkbox"/>	Springs	<u>2202</u>	None <input type="checkbox"/>
Livestock	<u>5230</u>	None <input type="checkbox"/>	Occupied Building	<u>1257</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

On March 29, 2019, Gracie Marquez with the Weld County LEPC was contacted regarding this incident. DCP Operating is the landowner. On March 14th a vac truck attempted to remove the condensate and snow mixture from the concrete secondary containment. Only 2 barrels were able to be removed due to the condensate and snow mixture was too frozen to be removed. The 2 barrels recovered were disposed at Complete HP Disposal in Platteville, CO. On March 15th, a vac truck was called out to remove the remaining condensate and snow melt mixture. Approximately 18 barrels of condensate and snow melt mixture was recovered and disposed at Complete HP Disposal in Platteville, CO. A sample was collected to try to determine the amount of condensate and snow melt contained in the secondary containment. A gringout field test was performed on the collected sample. The results indicated that 1/4 of the sample was condensate and 3/4 was water. Based on the field test results, 5 barrels of condensate was released into the concrete secondary containment when the fire tube leaked.

CORRECTIVE ACTIONS

#1	Supplemental Report Date: 03/19/2019
Cause of Spill (Check all that apply) <input type="checkbox"/> Human Error <input checked="" type="checkbox"/> Equipment Failure <input type="checkbox"/> Historical-Unknown <input type="checkbox"/> Other (specify) _____	
Describe Incident & Root Cause (include specific equipment and point of failure)	
<div>On March 13, 2019, a spill occurred from a fire tube leak that was discovered from the heater treater on the stabilized condensate tanks. Operations noticed smoke coming out of the stack that was white. Operations went to investigate and found a steady stream of condensate leaking out of the spark arrestor door which would indict a fire tube leak. Approximately 20 barrels of a mixture of condensate and snow was contained within the concret secondary containment.</div>	
Describe measures taken to prevent the problem(s) from reoccurring:	
<div>On March 13, 2019, Operations shutdown and bypassed the heater treater. On March 15th, Operations removed the fire tube and send it in for repairs.</div>	
Volume of Soil Excavated (cubic yards): 0	
Disposition of Excavated Soil (attach documentation) <input type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment <input type="checkbox"/> Other (specify) _____	
Volume of Impacted Ground Water Removed (bbls): 0	
Volume of Impacted Surface Water Removed (bbls): 0	

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)
☐ Work proceeding under an approved Form 27
Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Please also submit coorespondance to bshayes@dcpmidstream.com

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Chandler Cole
Title: Compliance Coordinator Date: 04/30/2019 Email: cecole@dcpmidstream.com

COA Type

Description

Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or further remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401978143	SPILL/RELEASE REPORT(SUPPLEMENTAL)
401989896	SITE MAP
401989900	SITE MAP
402025880	FORM 19 SUBMITTED

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)