

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2019

Submitted Date:

04/24/2019

Document Number:

688402006**FIELD INSPECTION FORM**Loc ID 320309 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
,		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203427	WELL	PR	11/01/2018	GW	001-08986	EHLER 34-11-1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign faded not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	05/24/2019
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash: PVC pipe and dead weeds on north side of separator.		
Corrective Action:	Comply with rule 603 f	Date:	05/08/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Deadman # & Marked	# 1		
Comment:	Guy line anchors not marked		

Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	05/15/2019
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:	Equipment not anchored or inadequately anchored			
Corrective Action:	Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.		Date:	05/24/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	48bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	shares containment with crude oil tank				
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Equipment not anchored or inadequately anchored				
Corrective Action:	Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.				
Date:	05/24/2019				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment: Birms are constructed out of gravel.					
Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.					Date: 05/24/2019
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	203427	Type:	WELL	API Number:	001-08986	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday April 24, 2019 at approximately 1243 hrs, I Randy Silver, Conducted an on-site inspection at a Great Western site Ehler #34-11-1, at API# 05-001-08986 in Adams county Colorado.</p> <p>While there, I observed Production site</p> <p>During the inspection, the following possible compliance issues were observed:</p> <p>Improper equipment anchoring: Rule 603 h (2) B Corrective action date of 5-24-19 See photos 6,8</p> <p>Placards faded: Rule 210 e Corrective action date of 5-24-19 See photo 5</p> <p>Guy line anchor: Rule 1003 a Corrective action date of 5-15-19 See photo 3</p> <p>Trash: Rule 603 f Corrective action date of 5-8-19 See photo 7</p> <p>Berms in flood plain: Rule 603 h(2)C Corrective action date of 5-24-19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402020637	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805559
688402007	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805549
688402008	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805550