

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2019

Submitted Date:

04/24/2019

Document Number:

688402011**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
320506 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271836	WELL	PR	01/01/2019	OW	001-09493	IVEY 16-11	PR
446639	TANK BATTERY	AC	07/15/2016		-	IVEY-61S68W 11SESE	AC

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	steel tubing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barb wire		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Equipment located in a flood plain. Inadequate berms.		
Corrective Action:	Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.		Date: 05/24/2019
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Tank located in view of county roads. Paint in disrepair.				
Corrective Action:	Paint tanks per Rule 804.				Date: 07/24/2019

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Tank located in a flood plain inadequate berms.			
Corrective Action:	Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.			Date: 05/24/2019

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 271836 Type: WELL API Number: 001-09493 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 446639 Type: TANK API Number: - Status: AC Insp. Status: AC**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday April 24, 2019 at approximately 1331 hrs, I Randy Silver, Conducted an on-site inspection at a KP Kyffman site Ivey #16-11, at API# 05-001-09493 in Adams county Colorado.</p> <p>While there, I observed Production site</p> <p>During the inspection, the following possible compliance issues were observed:</p> <p>Berms in flood plain: Rule 603 h(2)C Corrective action date of 5-24-19 See photos 2,3</p> <p>Visual Impact: Rule 804 Corrective action date of 7-24-19 See photos 4,5</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402020638	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805560
688402012	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805552
688402013	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805553