

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402020627

Date Received:

04/24/2019

## FIR RESOLUTION FORM

### CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Fischer, Alex

alex.fischer@state.co.us

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 688800485

Inspection Date: 03/26/2019

FIR Submit Date: 04/01/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 326167

Location Name: THOMAS JACQUEZ GAS UNIT E-N33N10W Number: 14NESE County: LA PLATA

Qtrqtr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.103177 Longitude: -107.898299

### FACILITY - API Number: 05-067- -00 Facility ID: 215984

Facility Name: THOMAS JACQUEZ E Number: 1

Qtrqtr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.103177 Longitude: -107.898299

### CORRECTIVE ACTIONS:

1 ☒ CA# 123735

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEL in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk

remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**2** ☒ CA# 123736

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**3** ☒ CA# 123737

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 04/02/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**4** ☒ CA# 123738

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 04/02/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**5** ☒ CA# 123739

Corrective Action: Maintain signs in a legible condition per Rule 210.e.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Operator Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

COGCC Decision: Approved via an AMI

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions completed see attached photos of work completed - Five gallon bucket emptied and stained soils were manually removed and disposed of in the BPX soil box to be remediated in bulk at IEI in Farmington NM. - Stained soils at truck load out for PBV were manually removed and taken to BPX soil box for bulk remediation at IE in Farmington NM - Stained / wet gravel at blow down valve on pipeline were cleaned up and deposited in soil box for bulk remediation at IEI - Sign was attached to cattle panel to ensure it will remain in place and not blow over again in windy conditions. Operations performed maintenance on equipment to stop any leaks. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: sabre.beebe@bpx.com

Signed:

Title: Compliance Specialist

Date: 4/24/2019 5:27:53 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402020627	FIR RESOLUTION SUBMITTED
402020628	Photos of work completed on location

Total Attach: 2 Files