

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100493



PHOTO 1: THE IMPACTED SOIL BETWEEN THE LIQUID RING COMPRESSOR AND THE SEPARATOR HOUSE WAS REMOVED FROM THE LOCATION.

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100493



PHOTO 2: THE IMPACTED SOIL BEHIND THE SEPARATOR HOUSE WAS REMOVED FROM THE LOCATION.

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100493



PHOTO 3: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100493



PHOTO 4: A RED POST WAS INSTALLED IN THE PRODUCTION PIT TO MARK THE TWO FOOT FREE BOARD LEVEL IN THE PIT.