

APACHE CANYON 35-06 API# 05-071-08540 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100455



PHOTO 1: THE ABSORBENT PADS THAT WERE ON THE SKID WERE REMOVED AND THE OIL ACCUMULATION WAS CLEANED UP.

APACHE CANYON 35-06 API# 05-071-08540 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100455



PHOTO 2: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR AND THE SOUND WALLS HAVE BEEN CLEANED UP.

APACHE CANYON 35-06 API# 05-071-08540 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100455



PHOTO 3: THE ABSORBENT PADS THAT WERE ON THE SKID WERE REMOVED IN COMPLIANCE WITH RULE 907.A.

APACHE CANYON 35-06 API# 05-071-08540 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100455



PHOTO 4: REPLACED THE PACKING TO ELIMINATE THE WATER LEAK. PACKINGS ARE SECURELY FASTENED IN COMPLIANCE WITH RULE 605.D.