

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402031548

Date Received:

05/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26580

Name of Operator: BURLINGTON RESOURCES OIL & GAS LP

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Larry Smith

Phone

832-486-2590

Email

larry.r.smith@conocophillips.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500032

Inspection Date: 04/19/2019

FIR Submit Date: 04/25/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BURLINGTON RESOURCES OIL & GAS LP

Company Number: 26580

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 454808

Location Name: Arkansas 4-64 3-2 Number: _____ County: _____

Qtrqr: NWS Sec: 3 Twp: 4S Range: 64W Meridian: 6
W

Latitude: 39.730092 Longitude: -104.544072

FACILITY - API Number: 05-005- -00 Facility ID: 454808

Facility Name: Arkansas 4-64 3-2 Number: _____

Qtrqr: NWS Sec: 3 Twp: 4S Range: 64W Meridian: 6
W

Latitude: 39.730092 Longitude: -104.544072

CORRECTIVE ACTIONS:

1 CA# 124597

Corrective Action: Comply with Rules 603.f. and 1003.f. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 04/19/2019

Response: CA COMPLETED

Date of Completion: 05/03/2019

Operator Comment: We have disked the location to kill weeds and have reseeded with the Arapahoe seed mix. Crippling and mulching operations completed by 05-07-19. See attached photos.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 124598

Corrective Action: Comply with Rule 1002.c. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 04/19/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment: anticipate completion of crib and mulch by 05-07-19.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 124599

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 04/19/2019

Response: CA COMPLETED

Date of Completion: 05/03/2019

Operator
Comment: BMP's have been repaired at ditches and inlet of sediment basin. See attached photos.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed, photo's attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larry Smith

Signed: _____

Title: Sr Regulatory Coordinator

Date: 5/3/2019 1:19:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402031846	Arkansas well site restoration 1
402031856	Arkansas site restoration 2
402031868	Arkansas site restoration 3
402031882	Arkansas site restoration 4
402031895	Arkansas site restoration 5
402031903	Arkansas site restoration 6
402031914	Arkansas site restoration 7
402031936	Arkansas site restoration 8

402031942	Arkansas site restoration 9
-----------	-----------------------------

Total Attach: 9 Files