

APACHE CANYON 24-04 API# 05-071-08687 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401815



PHOTO 1: THE LOCATION SIGN INCLUDING THE CORRECT EMERGENCY CONTACT INFORMATION WAS POSTED ON THE SEPARATOR HOUSE DOOR .

APACHE CANYON 24-04 API# 05-071-08687 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401815



PHOTO 2: THE DOOR TO THE SEPARATOR WAS REPAIRED AND REATTACHED TO THE SEPARATOR HOUSE.

APACHE CANYON 24-04 API# 05-071-08687 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401815



PHOTO 3: THE UNUSED (1) INCH PIPE WAS REMOVED FROM THE LOCATION.

APACHE CANYON 24-04 API# 05-071-08687 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401815



PHOTO 4: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 24-04 API# 05-071-08687 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401815



PHOTO 5: THE ABSORBENT PADS AND OIL ACCUMULATION WERE REMOVED FROM THE LIQUID RING SKID AND CLEANED UP.

APACHE CANYON 24-04 API# 05-071-08687 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401815



PHOTO 6: THE DEADMAN ANCHOR WAS MARKED WITH A RED POST.