

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 1



Pic 2 weeds trash.

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 3 weeds, trash.



Pic 4 stained soil

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 5 stained soil by motor



Pic 6 unused equipment sucker rods

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.8115, -104.20748, 4975.4ft, 230°
05/07/2019 13:45:08

Pic 7 weeds around tanks



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.8115, -104.20743, 4975.8ft, 86°
05/07/2019 13:45:14

Pic 8 weeds around seperator

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 9 possible leak separator house stained soil



Pic 10 stained soil

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 11 stained soil possible leak



Pic 12 stained soil overflowing tank

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 13 overflowing water tank



Pic 14 stained soil

Inspection Photos
Location Name: Thompson-Price #2
Location ID: 320156



Pic 15 stained soil