

APACHE CANYON 25-04 API# 05-071-06133 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100502



PHOTO 1: THE IMPACTED SOIL AROUND THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 25-04 API# 05-071-06133 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100502



PHOTO 2: THE FLUID ACCUMULATION WAS REMOVED FROM THE SKID.

APACHE CANYON 25-04 API# 05-071-06133 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100502



PHOTO 3: THE FLUID ACCUMULATION WAS REMOVED FROM THE RESERVOIR. THE IMPACTED SOIL AROUND THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.