

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402036795

Date Received:
05/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mack, Ronald

ronaldmack@tcenergy.us

Santistevan, Vince

719-845-2102/719-680-9705

vincasantistevan@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401825

Inspection Date: 04/11/2019

FIR Submit Date: 04/11/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308441

Location Name: GOLDEN EAGLE-633S67W Number: 17SESW County: LAS ANIMAS

Qtrqtr: SESW Sec: 17 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.166560 Longitude: -104.912800

FACILITY - API Number: 05-071- -00 Facility ID: 272124

Facility Name: GOLDEN EAGLE Number: 17-14

Qtrqtr: SESW Sec: 17 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.166560 Longitude: -104.912800

CORRECTIVE ACTIONS:

1 CA# 124176

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator
Comment:

The well head packings were securely fastened to stop the leak. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative:

2 CA# 124177

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A

Date: 05/11/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment:

The impacted soil around the well head has been removed from the location. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative:

3 CA# 124178

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907.

Date: 05/11/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment:

The impacted soil around the engine skid was removed from location. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/8/2019 2:55:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402036820	Photo Log
-----------	-----------

Total Attach: 1 Files