



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	06/02/2019
Type	DEBRIS		
Comment:	Debris/weeds: Dead weeds on location, around electric panel and inside PU base.		
Corrective Action:	Comply with rule 603 f	Date:	05/16/2019

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241700 Type: WELL API Number: 123-09489 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Thursday May 2, 2019 at approximately 1100hrs, I Randy Silver                      Conducted an on-site inspection at a KP Kauffman site, Elk Horn Company B #7, at                      API# 05-123-09489 in Weld County Colorado.                      While there, I observed a Well site.                      During my inspection, the following possible compliance issues were observed:                      Stained soil: rule 907 e Corrective action date of 6-2-19 See photo 5                      Debris/weeds: Rule 603 f Corrective action date of 5-16-19 See photos 1,2,4,6,7,8                      A follow up on this site inspection needs to be conducted to ensure the                      compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	05/02/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402030727	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813780">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813780</a>
688402087	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813766">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813766</a>