

Inspection Photos

Operator: Logos Operating
Location/API #: 067-05367
Date: 5-9-2019



Photo 1. View of the eastern project area from the northeastern corner facing southward. Cut slopes are eroding.



Photo 2. View of erosional channeling in the well pad cut-slope. Exposed roots, scouring, and sediment deposition indicate erosion.



Photo 3. View of the western project area from the western edge facing southward. Vegetation is sparse and erosion is occurring.



Photo 4. View of erosional channel approximately 2 feet wide and 1 foot deep within the western project area.