

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2019

Submitted Date:

05/21/2019

Document Number:

697500141

FIELD INSPECTION FORM

Loc ID 456537 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10542
Name of Operator: CUB CREEK ENERGY
Address: 200 PLAZA DRIVE SUITE 100
City: HIGHLANDS State: CO Zip: 80129

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Baily, Scott		scott.baily@cub-creek.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456537	LOCATION	AC			-	OLANDER PAD	CI

General Comment:

[This is a Construction and Stormwater Inspection in response to Form 42: Notice of construction- Document #402041032.](#)

Location Construction

Location ID: 456537 CDP: _____

Comment: At the time of this inspection, Operator has only initiated stormwater installation- see stormwater section for more details. Per the Operator Guidance Rule 316C/Form 42 Field Operations Notice, for a change of 1 – 5 days, the operator contacts the Area Field Inspector via email and provide the revised date and time. For a change greater than 5 days, the operator submits a Form 42 – Update with the revised date and time.

Corrective Action: _____ **Date:** _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ **Date:** _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 456537 Type: LOCATION API Number: - Status: AC Insp. Status: CI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator failed to install a tracking device BMP. Operator is tracking out sediment and rutting up the entrance. Refer to the attached inspection photos.

Note: It appears silt fence stakes have been installed too far apart. Per Rule 1002.f., Operator shall install stormwater BMPs per good engineering practices.

Corrective Action: Corrective action date is the date that operations started based off the Form 42 and when tracking device BMPs should have been installed.

Date: 05/15/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697500142	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4828475