

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402050765

Date Received:

05/21/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Daniel Lapp

Phone

970-629-9525

Email

regulatory@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679703154

Inspection Date: 02/28/2019

FIR Submit Date: 02/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 315688

Location Name: RANGELY SOUTH FED-61S102W Number: 3E2NE County: RIO BLANCO

Qtrqtr: E2NE Sec: 3 Twp: 1S Range: 102W Meridian: 6

Latitude: 39.998780 Longitude: -108.827220

FACILITY - API Number: 05-103-00 Facility ID: 231353

Facility Name: RANGELY SOUTH FED Number: 18-3-1-102

Qtrqtr: E2NE Sec: 3 Twp: 1S Range: 102W Meridian: 6

Latitude: 39.998780 Longitude: -108.827220

CORRECTIVE ACTIONS:

1 CA# 122803

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 04/03/2019

Response: CA COMPLETED

Date of Completion: 05/20/2019

Operator Comment: Berm not needed

COGCC Decision: _____

Date: 04/03/2019

Date of Completion: 05/20/2019

Removed unused blowdown tank and piping	
---	--

COGCC Decision:

--

Corrective action resolved

Signed:

Date: 5/21/2019 11:44:17 AM

402050770	RSF 18-3
-----------	----------

Page 2 of 2