

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402051782

Date Received:

05/21/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sabre Beebe

970-779-9398

sabre.beebe@bpx.com

Inspections, All

SanJuanCOGCC@bp.com

Fischer, Alex

alex.fischer@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800391

Inspection Date: 12/10/2018

FIR Submit Date: 12/11/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326271

Location Name: RICHARDSON GAS UNIT G-N34N8W Number: 1SWSE County: LA PLATA

Qtrqtr: SWSE Sec: 1 Twp: 34N Range: 8W Meridian: N

Latitude: 37.240140 Longitude: -107.693600

FACILITY - API Number: 05-067-00 Facility ID: 216146

Facility Name: RICHARDSON G Number: 1

Qtrqtr: SWSE Sec: 1 Twp: 34N Range: 8W Meridian: N

Latitude: 37.240140 Longitude: -107.693600

CORRECTIVE ACTIONS:

1 CA# 120929

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 01/11/2019

Response: CA COMPLETED

Date of Completion: 05/02/2019

Impacted soils excavated around the wellhead, placed in containment bag and transported to the IEI soil box at the BPX office to be remediated in batch remediation. See attached photos. Excavation holes back filled with

Operator
Comment: clean soils.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Impacted soils excavated around the wellhead, placed in containment bag and transported to the IEI soil box at the BPX office to be remediated in batch remediation. See attached photos. Excavation holes back filled with clean soils.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/21/2019 5:32:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402051784	Follow up form and photos
-----------	---------------------------

Total Attach: 1 Files