

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402054806

Date Received:

05/24/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name Phone

Rowley, Darren

Email

drowley@logosresourcesllc.com

Sessions, Tamra

tsessions@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900103

Inspection Date: 03/18/2019

FIR Submit Date: 04/04/2019

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325235

Location Name: ESPINOSA-N32N6W Number: 16NWSW County: LA PLATA

Qtrqr: NWS Sec: 16 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.015750 Longitude: -107.510790

FACILITY - API Number: 05-067- -00 Facility ID: 214370

Facility Name: ESPINOSA Number: 1

Qtrqr: NWS Sec: 16 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.015750 Longitude: -107.510790

CORRECTIVE ACTIONS:

1 CA# 123876

Corrective Action: Remove and properly dispose of debris.

Date: 05/06/2019

Response: CA COMPLETED

Date of Completion: 05/21/2019

Operator Comment: All of the Debris including the land owners pipe has been removed from the area on and around the well pad.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 123877

Corrective Action: Remove and properly abandon unused flowlines.

Date: 05/06/2019

Response: CA COMPLETED

Date of Completion: 05/21/2019

Operator
Comment:

All of the Debris including the land owners pipe has been removed from the area on and around the well pad.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 123878

Corrective Action: Revegetation needs to be installed within portions of the project area that do not meet the COGCC 80 percent revegetation standard. Mulching, slope stabilization, and cattle/livestock exclusion may be needed for successful vegetation establishment.

Date: 05/18/2019

Response: CA COMPLETED

Date of Completion: 05/21/2019

Operator
Comment:

All disturbed soil has been re-seeded and mulched. See photos.

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 123879

Corrective Action: Erosion controls and stabilization measures are needed throughout the project area. Revegetation will help stabilization issues; however, erosion and sediment controls are needed until stabilization is achieved.

Date: 05/04/2019

Response: CA COMPLETED

Date of Completion: 05/21/2019

Operator
Comment:

Erosion and sediment controls have been installed on and around the well pad.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: _____

Title: Env/Reg Technician

Date: 5/24/2019 9:03:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402054816	Photos
402054818	Photos
402054820	Photos
402054834	Photos
402054835	Photos
402054836	Photos

Total Attach: 6 Files