

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402055849

Date Received:
05/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 9 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Stephen M Strachan

Phone

303-790-9115

Email

sms@strachanexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900683

Inspection Date: 05/15/2019

FIR Submit Date: 05/16/2019

FIR Status: _____

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC

Company Number: 83130

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 324831

Location Name: FRAZEE-619S50W Number: 6NWNW County: KIOWA

Qtrqr: NWN Sec: 6 Twp: 19S Range: 50W Meridian: 6
W

Latitude: 38.438830 Longitude: -103.060030

FACILITY - API Number: 05-061- -00 Facility ID: 213004

Facility Name: FRAZEE Number: 2-6

Qtrqr: NWN Sec: 6 Twp: 19S Range: 50W Meridian: 6
W

Latitude: 38.438830 Longitude: -103.060030

CORRECTIVE ACTIONS:

1 CA# 125236

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 06/15/2019

Response: CA COMPLETED

Date of Completion: 05/25/2019

Operator Comment: Berms were improved. Please refer to attached photos.

COGCC Decision: _____

COGCC
Representative:

2 CA# 125237

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area
COGCC EPS

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 05/25/2019

Operator Comment: We are in receipt of the inspection as of 5/16/19, Thursday evening, with a compliance date set at 5/20/19, Monday. The soil staining shown in Photo #6, well head and pump, appears to be localized spotting of oily waste; the spotting in Photo #9, in a storage shed, is of unknown origin and may be related to recent rains. We believe this staining at the well head, pump and shed should be allowed a 30-day cleanup period as they are localized, which would allow for contractor engagement and sufficient time to work the clean up. As today is Friday May 17, with the weekend approaching, finding contractors and arranging for cleanup and disposal by Monday, an unreasonable request. 30 days will allow for a diligent and prudent approach to clean up and disposal.

Oil stained soil has been cleaned up around wellhead, pump jack and storage shed. Soil has been isolated in a plastic lined containment. Samples were taken May 25 and will be submitted to the lab recommended by the commercial disposal site. Upon acceptance by the disposal site, the stained soil will be gathered, removed and disposed of.

COGCC Decision:

COGCC
Representative:

6 CA# 125241

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 06/15/2019

Response: CA COMPLETED

Date of Completion: 05/25/2019

Operator Comment: All fencing at the Frazee #2-6 location were tightened and straightened. Of note, no cattle have been inside any of the enclosures for the last 39 years. Please refer to the attached photos.

COGCC Decision:

COGCC
Representative:

7 CA# 125242

Corrective Action: Comply with Rule 603.f .
Mark and repair or remove.

Date: 06/15/2019

Response: CA COMPLETED

Date of Completion: 05/25/2019

Operator Comment: The pipe riser in question is an active gathering line drip. Road base was added to the site where cattle gather, a heavy steel pen was added to protect the riser, a pipeline marker was added, and the riser was inspected and straightened out. No leaks detected. Please see attached photos.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: As of May 25, berms have been improved; fences repaired; oil stained soil from around wellhead and pump jack as well as the storage shed, has all been picked up and stored in a bermed plastic lined containment on site; samples were taken on May 25th for analysis, and when results are submitted to commercial disposal and soil is accepted, all stained soil will be removed and disposed of. Pumpers are in the process of identifying recyclers for unused equipment (Our previous recycler passed away in February 2019). Met with pumpers Saturday May 25 to discuss remaining work.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Stephen M Strachan

Signed: _____

Title: President

Date: 5/26/2019 5:07:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402055852	Photo Update for FIR
-----------	----------------------

Total Attach: 1 Files