

Pit Status Evaluation Form

Pit Overview:

Pit Name: Johnson 1	Facility ID: 118037
Current Status: Unknown	Status Date:
Current Operator: Abraxas Petroleum Op No. 400	
Updated Operator: Abraxas Petroleum Op No. 400	
Form 15 Pit Permit Doc #: 383748	Permit Date: 1/11/1989
Related Facilities: none	

County: Weld			
Township: 8N	Range: 56W	Section: 10	QQ: SENW
Original Latitude/ Longitude: 40.677217 / -103.630558			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
Not changed, no pits visible in air photos dating to 1999			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|--|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 383748 | Date: 1/11/1989 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 383748 | Date: 7/27/1989 |
| Doc #: 239639 | Date: 4/27/1995 |
| Doc #: | Date: |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input checked="" type="checkbox"/> Form 4 Sundry Notice – Doc #: 239641 | Date: 12/26/1990 |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 12/18/1990

Timing of Pit Closure:

Pit was closed with plugging and abandonment of well in 1990.

Pit Status Review Summary:

Pit was closed in accordance with COGCC Rules in effect at time of pit closure. Site passed a reclamation inspection in 1995.