

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2019

Submitted Date:

06/03/2019

Document Number:

689900775**FIELD INSPECTION FORM**
 Loc ID 307376 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 21603 HIGHWAY 12City: TRINIDAD State: CO Zip: 81082**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ediefitzgerald@tcenergy.us	
		robfoos@tcenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217563	WELL	TA	06/20/2016	GW	071-06340	APACHE CANYON 17-13	RI

General Comment:

This is a follow up of the previous inspection #689900522. Corrective action of previous inspection has not been performed. It appears locates were being performed further up the canyon along the road. Further down the road there were no signs of locates done yet if required. Attached photos show road issues down toward the beginning of the canyon that will need to be repaired.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: There is an erosion channel that developed at the southeast side of the location along the access road. There is sediment migration from the cut slope. A ditch at the base of the cut slope may be needed to retain sediment. (New comment) There is erosion issues further down the road from the location that needs to be repaired. See Attached Photos</p> <p>Corrective Action: Install or repair required BMPs per Rule 1002.f. Date: 05/03/2019</p> <p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900776	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838678