

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

05/30/2019

Document Number:

696900002**FIELD INSPECTION FORM**
 Loc ID 461013 Inspector Name: CHESSON, BOB On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Axelson, John		john.axelson@state.co.us	
Medina, Justin		justin.medina@state.co.us	
Liesenfeld, Zack		Zack.Liesenfeld@pdce.com	
Olsson, Karen		Karen.Olson@pdce.com	

General Comment:

Stormwater BMP unable to handle unusual heavy rainfall on 5/27. Fluid left site on southern end of site (natural drainage course). Operator left e-mail on morning of 5/28 and followed with initial form 19 Spill/Release report (DOC #402057468; Spill Release Point #464686) on AM of 5/29. See attached inspection photos.

Operator instructed to file a Supplemental Form 19 with proposed or completed clean-up actions by 6/6/19. Spill clean-up actions must be completed within 60 days from 5/29/19 or operator must submit a Form 27 Remediation Work Plan to close this spill.

Location**Lease Road:**

Type	Access		
comment:	Well maintained.		
Corrective Action	L	Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☒

Spills:				
Type	Area	Volume		
Other		>= 5 bbls		
Comment:	Stormwater BMP unable to handle unusual heavy rainfall on 5/27. Fluid left site on southern end of site (natural drainage course). Operator left e-mail on morning of 5/28 and followed with initial form 19 Spill/Release report (DOC #402057468; Spill Release Point #464686) on AM of 5/29.			
Corrective Action:	File a Supplemental Form 19 with proposed or completed clean-up actions by 6/6/19. Spill clean-up actions must be completed within 60 days from 5/29/19 or operator must submit a Form 27 Remediation Work Plan to close this spill.			Date: 06/06/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: 10

Comment: Stormwater BMP unable to handle unusual heavy rainfall on 5/27. Fluid left site on southern end of site (natural drainage course). Operator left e-mail on morning of 5/28 and followed with initial form 19 Spill/Release report (DOC #402057468; Spill Release Point #464686) on AM of 5/29.

Corrective Action: File Supplemental Form 19 with proposed or completed clean-up actions by 6/6/19. Spill clean-up actions must be completed within 60 days from 5/29/10 or operator must submit a Form 27 Remediation Work Plan to close this spill.

Date: 06/06/2019

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

COGCC Comments

Comment

User

Date

Conducted inspection of spill/release. See attached photos.

chessonr

05/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402059202	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835316
696900003	Photo collection with comments.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835315