

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2019

Submitted Date:

06/15/2019

Document Number:

694400194**FIELD INSPECTION FORM**
 Loc ID 427262 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427262	LOCATION	AC			-	PAVISTMA PAD	AC

General Comment:

Inspected FacilitiesFacility ID: 427262 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

Corrective Action:

Date:

ComplaintComment: Inspection in response to complaint. 18#200447439/200447437Field Inspector Assigned: Adam KraichComplaint Received:Date: 6/14/2019Complaint Contacted:Date: 6/14/2019 @ 8:44am. No response, left VM, no call back for 24 hours or more.Location #: 427262Inspection Document #: 694400194Nature of complaint: NoiseField Inspector Actions:On 6/14/2019, I received a complaint in regard to noise coming from the Pavistma production facility, owned and operated by Extraction Oil & Gas.On 9/14/2019, I performed an inspection of the Pavistma location, that was in production at the time of inspection.After meeting with Extraction's production operator, it was discovered that the night prior, as the production facility experienced a high line pressure event, which resulted in pressure relief valves on compression infrastructure to activate and reset until operators would shut down, and de-energize equipment.Filed operations have since changed their operating procedure to eliminate reoccurrence in the future.I did not perform a sound study as the upset condition suspected to be the source of the noise has since ceased.No violation of COGCC rules were observed at the time of the inspection.All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400195	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4851085