

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2019

Submitted Date:

06/10/2019

Document Number:

697300151**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Graber, Candice (Nikki) _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Spills&Remediations		COGCCSpillRemediation@pdce.com	
Olsson, Karen		Karen.Olson@pdce.com	
Inspections, All		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448348	SPILL OR RELEASE	CL	05/04/2017		-	Bauer 5; 12, 21-4	EI

General Comment:

This is an environmental inspection in response to spill Document #402067403 reported by Operator on 6/6/2019.

Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Overall good.

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Orange construction fencing surrounding excavation.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	Excavation open at the time of inspection. Appears impacted soil has been trucked off location for disposal; some soil stockpiled.			
Corrective Action	Provide all E&P waste disposal documentation required by Rule 907.b(2).			Date: 07/07/2019

Spill/Remediation:

Comment:	Groundwater observed in bottom of excavation.			
Corrective Action:	Operator shall define the vertical and horizontal extent of impacts to soil and groundwater. Samples shall be collected in accordance with Rule 910.b and reported in a Subsequent F19 or Form 27.			Date: 07/07/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402069902	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845347
697300152	Water in Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845345
697300153	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845346