



STATE OF
COLORADO

McFarland - DNR, Nick <nick.mcfarland@state.co.us>

6 SRA - HSR Sekich A 9-17 - API: 05-123-18820

Geno, Kristina <Kristina.Geno@anadarko.com>
To: "McFarland - DNR, Nick" <nick.mcfarland@state.co.us>
Cc: "Crumrine, Tim" <Tim.Crumrine@anadarko.com>

Fri, Jun 21, 2019 at 2:49 PM

Good afternoon Nick,

I did track down an answer to your question. Unfortunately there was a miscommunication between the field and the office and therefore the casing was not cut at the correct depth of 890'.

Unfortunately, the WBD had been updated but not the written procedure. Our Wellsite Supervisor happened to be following the written procedure and therefore that cutting depth was missed.

I realize this is not the best answer, so please let me know if you have further questions or concerns.

Thank you,

Kristina Geno

Regulatory Affairs – DJ Basin Compliance

Anadarko Petroleum Corporation

720.929.6824 - Direct

720.218.9662 - Cell

From: McFarland - DNR, Nick <nick.mcfarland@state.co.us>

Sent: Thursday, June 20, 2019 5:45 PM

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

[Redacted]

P 303.894.2100 x5682 | F 303.894.2109

nick.mcfarland@state.co.us | www.colorado.gov/cogcc

=

Nick McFarland

Contract Petroleum Engineer

[Redacted]

P 303.894.2100 x5682 | F 303.894.2109

nick.mcfarland@state.co.us | www.colorado.gov/cogcc

=

Nick McFarland

Contract Petroleum Engineer

[Redacted]

[Quoted text hidden]