

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402085434

Date Received:

06/24/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Deb Lemon

7205507507 ext 105

dlemon@mustangresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692401002

Inspection Date: 05/21/2019

FIR Submit Date: 06/04/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MUSTANG RESOURCES LLC

Company Number: 10550

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

LOCATION - Location ID: 323788

Location Name: MOORE-66S94W Number: 27SENE County: \_\_\_\_\_

Qtrqr: SENE Sec: 27 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.499339 Longitude: -107.867169

FACILITY - API Number: 05-045-00 Facility ID: 323788

Facility Name: MOORE-66S94W Number: 27SENE

Qtrqr: SENE Sec: 27 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.499339 Longitude: -107.867169

CORRECTIVE ACTIONS:

1 CA# 125804

Corrective Action: Remove Debris from Location.

Date: 06/23/2019

Response: CA COMPLETED

Date of Completion: 06/21/2019

Operator Comment: Work completed by 6/21/2019.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 125805

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/02/2019

Response: CA COMPLETED

Date of Completion: 06/21/2019

Operator Comment: Mustang has made every effort to comply with Rule 1002.f. However, the surface owner has requested repeatedly that Mustang not use weed killer on his land and that Mustang or any of its contractors do not compact the soils. Mustang requests that COGCC work directly with the surface owner, Mr. Brian Sperry, to resolve conflicting outcomes. Mr. Sperry can be reached at 303-514-1056. Please see Attachment #1 to this FIRR.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see comments under CA response.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deb Lemon

Signed: \_\_\_\_\_

Title: Regulatory Manager

Date: 6/24/2019 1:18:19 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402085438	Surface owner sign on pad
402085439	Entrance to pad
402085440	Pad Photo #1
402085442	Pad Photo #2
402085444	Pad Photo #3
402085447	Wellhead sign
402085449	Pad PHoto #4

Total Attach: 7 Files