

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402092188

Date Received:

07/01/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Paluch, Kelly

Phone

970-364-2812

Email

cogccinspections@gwogco.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688402006

Inspection Date: 04/24/2019

FIR Submit Date: 04/24/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GREAT WESTERN OPERATING COMPANY LLC

Company Number: 10110

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320309

Location Name: EHLER-61S68W Number: 11SWSE County: ADAMS

Qtrqr: SWSE Sec: 11 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.973703 Longitude: -104.965775

FACILITY - API Number: 05-001- -00 Facility ID: 203427

Facility Name: EHLER Number: 34-11-1

Qtrqr: SWSE Sec: 11 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.973703 Longitude: -104.965775

CORRECTIVE ACTIONS:

1 CA# 124569

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: After discussion with inspector the battery has been deemed NOT in a floodplain.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 124570

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator  
Comment: After discussion with inspector the battery has been deemed NOT in a floodplain.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 124571

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator  
Comment: After discussion with inspector the battery has been deemed NOT in a floodplain.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**4** CA# 124572

Corrective Action: Install sign to comply with Rule 210.e.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator  
Comment: Signage was installed

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**5** CA# 124573

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 05/15/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator  
Comment: Anchore removed from location

COGCC Decision: \_\_\_\_\_

\_\_\_\_\_

--

Date: 7/1/2019 9:29:39 AM

<u>Document Number</u>	<u>Description</u>
402092194	ANCHOR REMOVED
402092200	WELLHEAD SIGNAGE
402092204	TRASH REMOVED

Page 3 of 3